

INSPECTION IMAGES

HOUSE SLOPES OVERVIEWS

Front - Roof Overview

January 18, 2022



Right - Roof Overview

January 18, 2022



INSPECTION IMAGES

Front Slope - P.A./Contractor Considerations
January 18, 2022



Front Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Front Slope - P.A./Contractor Considerations
January 18, 2022



Front Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Front Slope - P.A./Contractor Considerations
January 18, 2022



Front Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Front Slope - P.A./Contractor Considerations
January 18, 2022



Front Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Front Slope - P.A./Contractor Considerations
January 18, 2022



Front Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Front Slope - P.A./Contractor Considerations

January 18, 2022



RIGHT SLOPE

Right Slope - Test Square Overview

January 18, 2022



INSPECTION IMAGES

Right Slope - Damage Assessment

Hail - 0

Wind - 0

January 18, 2022



Right Slope - Roof Condition

Good Condition

January 18, 2022



INSPECTION IMAGES

Right Slope - Roof Condition

Good Condition

January 18, 2022



Right Slope - Roof Condition

Good Condition

January 18, 2022



INSPECTION IMAGES

Right Slope - Roof Condition

Good Condition

January 18, 2022



Right Slope - Roof Condition

Good Condition

January 18, 2022



INSPECTION IMAGES

Right Slope - Roof Condition

Good Condition

January 18, 2022



Right Slope - Roof Condition

Good Condition

January 18, 2022



INSPECTION IMAGES

Right Slope - Roof Condition

Fair Condition

Deterioration

January 18, 2022



Right Slope - Roof Condition

Fair Condition

Deterioration

January 18, 2022



INSPECTION IMAGES

Right Slope - P.A./Contractor Considerations
January 18, 2022



Right Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Back Slope - Roof Condition

Good Condition

January 18, 2022



Back Slope - P.A./Contractor Considerations

January 18, 2022



INSPECTION IMAGES

Back Slope - P.A./Contractor Considerations

January 18, 2022



Back Slope - P.A./Contractor Considerations

January 18, 2022



INSPECTION IMAGES

Back Slope - P.A./Contractor Considerations
January 18, 2022



Back Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Back Slope - P.A./Contractor Considerations
January 18, 2022



Back Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Back Slope - P.A./Contractor Considerations
January 18, 2022



Back Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Back Slope - P.A./Contractor Considerations
January 18, 2022



Back Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Back Slope - P.A./Contractor Considerations

January 18, 2022



Back Slope - P.A./Contractor Considerations

January 18, 2022



INSPECTION IMAGES

Accessory - Back Slope

Box Vent

Aluminum

Storm related damage caused by hail

Unsealed Condition

January 18, 2022



Accessory - Back Slope

Power Vent

Galvanized

No Damage

Size: Medium

January 18, 2022



INSPECTION IMAGES

Left Slope - Roof Condition

Good Condition

January 18, 2022



Left Slope - P.A./Contractor Considerations

January 18, 2022



INSPECTION IMAGES

Left Slope - P.A./Contractor Considerations

January 18, 2022



Left Slope - P.A./Contractor Considerations

January 18, 2022



INSPECTION IMAGES

Left Slope - P.A./Contractor Considerations

January 18, 2022



Left Slope - P.A./Contractor Considerations

January 18, 2022



INSPECTION IMAGES

Left Slope - P.A./Contractor Considerations
January 18, 2022



Left Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Left Slope - P.A./Contractor Considerations
January 18, 2022



Left Slope - P.A./Contractor Considerations
January 18, 2022



INSPECTION IMAGES

Left Slope - P.A./Contractor Considerations
January 18, 2022

